

# WEST Search History





DATE: Tuesday, January 04, 2005

| <u>Hide?</u>             | <u>Set Name</u>                  | <u>Query</u>                                   | <u>Hit Count</u> |
|--------------------------|----------------------------------|--|------------------|
|                          | <i>DB=PGPB; PLUR=YES; OP=ADJ</i> |  |                  |
| <input type="checkbox"/> | L25                              | I21 and I22 and I19                            | 2                |
| <input type="checkbox"/> | L24                              | L23 and I19                                    | 5                |
| <input type="checkbox"/> | L23                              | microprocessor same I21                        | 14               |
| <input type="checkbox"/> | L22                              | (chair lift) or chairlift or (wheelchair lift) | 175              |
| <input type="checkbox"/> | L21                              | interlock same vehicle                         | 434              |
| <input type="checkbox"/> | L19                              | @pd>20040809                                   | 114365           |
|                          | <i>DB=USPT; PLUR=YES; OP=ADJ</i> |  |                  |
| <input type="checkbox"/> | L18                              | L17 and I1                                     | 1                |
| <input type="checkbox"/> | L17                              | I8 same (parking brake)                        | 80               |
| <input type="checkbox"/> | L16                              | L15 not I14                                    | 9                |
| <input type="checkbox"/> | L15                              | (I10 or I11 or I12) and vehicle and I1         | 9                |
| <input type="checkbox"/> | L14                              | microprocessor and I13                         | 7                |
| <input type="checkbox"/> | L13                              | (I10 or I11 or I12) and I8                     | 35               |
| <input type="checkbox"/> | L12                              | wheelchair lift                                | 278              |
| <input type="checkbox"/> | L11                              | chairlift                                      | 138              |
| <input type="checkbox"/> | L10                              | chair lift                                     | 510              |
| <input type="checkbox"/> | L9                               | L8 and I7                                      | 0                |
| <input type="checkbox"/> | L8                               | interlock same vehicle                         | 2365             |
| <input type="checkbox"/> | L7                               | I1 and (I2 or I3 or I4 or I5 or I6)            | 128              |
| <input type="checkbox"/> | L6                               | 187/306.ccls.                                  | 57               |
| <input type="checkbox"/> | L5                               | 414/545,557.ccls.                              | 313              |
| <input type="checkbox"/> | L4                               | 340/456,457.3.ccls.                            | 192              |
| <input type="checkbox"/> | L3                               | 307/10.1.ccls.                                 | 1871             |
| <input type="checkbox"/> | L2                               | 701/36,45,49.ccls.                             | 1484             |
| <input type="checkbox"/> | L1                               | @pd>20040809                                   | 74267            |